



# Multiple design slave cylinders installed by vehicle manufacturers


The diameter ( $\varnothing$ ) of the hydraulic connections are the main difference between them.

**Nissan**, Almera II, Micra III, Note, Qashqai, Tida.

**Dacia**, Duster, Logan, Logan Express-Pick-up-MCV, Sandero.

**Renault**; Clio II-III- Grandtour, Fluence, Kangoo & Rapid, Laguna II, Megane II-III, Modus, Scenic- Grand Scenic II, Thalia, Twingo.


**Design 1 – Part Number Enclosed**



*Design 2 – Different Part Number*



*Design 3 – Different Part Number*



*Design 4 – Different Part Number*



When replacing cylinders, please ensure the diameters of the hydraulic connections on the old and new parts match.  
If the wrong hydraulic connection is installed, it will cause leaks and system failure.